

# PONPE 219BT

The device uses high-precision, low-power digital sensors with wide measuring range and high accuracy. Press the key under the screen to power on, hold down the key long for power off.

## Function

- Bluetooth for connect
- Power off automatically
- Dedicated APP
- Easy to carry and operate
- High-precision
- Save and share data



Save and share data  
JPG or Excel files



## Product Parameters

### Wind speed measurement


Wind speed unit	Range	Resolution	Accuracy
m/s	1~25.0	0.01	± (3%+0.2m/s)
km/h	3.6~90.0	0.1	± (3%+0.8km/h)
ft/min	196~4921	1	± (3%+40ft/min)
Knots	1.9~48.5	0.1	± (3%+0.4knots)
MPH	2.2~55.9	0.1	± (3%+0.4MPH)

### Wind temperature measurement

Unit	Range	Resolution	Accuracy
°C	0~50°C	0.1	±2°C

### General technical data

Automatic shutdown	About 15 minutes
Atmospheric pressure	500mb~2Bar
Operating temperature	0~50°C
Storage temperature	-10~60 °C
Storage humidity	0~75%RH, no condensation
Power supply	4x1.5V, AAA batteries
Size	175mmx45mmx26mm
Weight	82g



	A	B	C
	Date Time	Temperature	Wind speed
1			
2	07.03.2561 19:08:31	25.7	5.05
3	07.03.2561 19:08:32	25.7	5.05
4	07.03.2561 19:08:33	25.7	5.05
5	07.03.2561 19:08:34	25.7	4.47
6	07.03.2561 19:08:35	25.7	4.75
7	07.03.2561 19:08:36	25.6	4.75
8	07.03.2561 19:08:37	25.6	4.38
9	07.03.2561 19:08:38	25.6	4.38
10	07.03.2561 19:08:39	25.6	4.38
11	07.03.2561 19:08:40	25.6	4.38
12	07.03.2561 19:08:41	25.6	4.38
13	07.03.2561 19:08:42	25.6	4.38
14	07.03.2561 19:08:43	25.6	4.38
15	07.03.2561 19:08:44	25.6	4.38
16	07.03.2561 19:08:45	25.6	4.38