

ponpe

INSTRUMENTS

Thermometer

เครื่องวัดอุณหภูมิ

PONPE 421TK



Features

- 4 digits Large LCD display
- Celsius and Fahrenheit selectable
- Low battery indication
- Data Hold function mode
- Auto power-off

Thermometer

เครื่องวัดอุณหภูมิ

PONPE 421TK

Technical Parameters

Temperature range: -200 ~ 1370 °C (-328 ~ 2498 °F)
Accuracy: $\pm(1\%+1^{\circ}\text{C})$; $\pm(1\%+2^{\circ}\text{F})$
Resolution: 0.1 °C & 0.1 °F
Type of temperature measuring: K
Sampling rate: 2.5 times per second
Operating Temperature: 0 ~ 40 °C (32 ~ 104 °F)
Operating Humidity: 0 ~ 70 % (R.H.)
Input protection: 60V DC or 24V AC maximum input voltage on any combination input pins
Input connector: accept standard miniature thermocouple connectors
Battery: 4 x 1.5V AAA battery
Weight: 205g (include battery)
Dimension: 73x146x33mm



THERMOCOUPLE TYPE K

Probe (ชี้อัดัม)

PONPE 421PR : K type 4x200 mm
Range : -50 ~ 500 °C

